

INDEX OF ThunderEnlightening ARTICLES

<u>SUBJECT OF ARTICLE</u>	<u>ISSUE(S)</u>	<u>SUBJECT OF ARTICLE</u>	<u>ISSUE(S)</u>
ACCELERATION-IMPROVING	14	-CARBURETOR, REASON TO CHANGE DISTRIBUTOR	19
ALIGNMENT TIPS.....	15	-CAMSHAFT PREMATURE WEAR PROBLEM FIX	20
BATTERY		ENGINE (CONTINUED)	
-CABLE ROUTING & RETAINERS	13	-COLOR-CORRECT	3
-CABLES-GAUGE & ENDS	4	-COOLONG-OVERHEATING TIP	17
-COLORS	11	-CRANKSHAFT IDENTIFICATION.....	8
-WINTERTIME CARE	5	-DISTRIBUTOR IDENTIFICATION.....	22
BEARINGS-INSTALLATION TIPS.....	14	-DISTRIBUTOR-NO GASKET.....	7,21
BODY PANELS-ROCKERS-INSTALLING.....	3	-DISTRIBUTOR, REASON TO CHANGE WITH NEW CARB.....	19
BRAKES-CENTERING BRAKE SHOES.....	17	-EXHAUST MANIFOLDS-	
BRAKE LIGHTS-MECHANICAL.....	1	-BURNING STEERING COLUMN SEAL.....	10
BUMPERS-RUST PROBLEMS.....	13	-PROPER TIGHTENING	10
CASCO		-FUEL FILTER-CLOGGING UP	2
-ABRASIVE WATER JET	15	-DAMAGED BY BLENDED FUELS.....	22
-ANNIVERSARY	7,16,21	-GROUND-GETTING A GOOD ONE	4
-BRAD FULLER	17	-HEAD GASKETS-INSTALL CORRECTLY	1,9
-EARLY HISTORY	21	-HEAD REMOVAL TIPS	15
-EXTENDED OFFICE HOURS	22	-IDENTIFYING SIZE BY CRANKSHAFT END	8
-JOHN LONSBURRY	17	-IDLE PROBLEMS-OPEN SECONDARIES	6
-NEW PRESIDENT	12	-LOW COMPRESSION, REASONS FOR.....	19
-ON-LINE ORDERING NOW AVAILABLE.....	17	-NOW THAT IT IS OUT	21
-RESTORATIONS PLUG	4	-OIL PASSAGES-UNBLOCKING	2
-TECHNICAL ASSISTANCE.....	8	-OIL PRESSURE WARNING LAMP	14
-SMALL BUSINESS OF THE YEAR AWARD.....	9	-OIL PRIMING	1
CIGARETTE LIGHTER-RESETTABLE FUSE	1	-OIL SUPPLEMENT (ZDDP+).....	20
CLASSIFIED FOR SALE ADS-FREE.....	12,16	-OVERHEATING-CLEANING BLOCK	7
CLOCK KNOB REMOVAL.....	11	-REAR MAIN SEALS-CALL FOR DATA.....	6
CONTINENTAL KIT BAND TENSION	22	-REAR MAIN SEAL-FIXING LEAKS BY ALIGN BORING.....	10
COIL SPRING REMOVAL	17	-REMOVAL-STEP BY STEP PROCEDURE	20
CONCOURS RULE BOOK.....	1	-STARTS BUT WON'T RUN.....	4
CONVERTIBLE TOP		-TOP DEAD CENTER-FINDING	15
-CANVAS FADING	1	-TUNE-UP SPECS	4,9
-DIFFERENCES EARLY/LATE	6	-VALVE COVER INSTALLATION	21
-IDENTIFYING PINS	6	-VALVE LASH ADJUSTMENT TECHNIQUE.....	13,16
-REPLACING TACK STRIPS & RETAINERS	19	-WATER PUMP BAFFLE-CALL FOR DATA	6
-STOWING TIPS	19	-WATER PUMP-NOISY.....	14
COST OF RESTORATION PARTS	15	EMBLEMS-FRONT-CORRECT POSITION	4
CTCI INFORMATION	1,6,7,8,9,10,11,16	EMBLEMS-TEMPLATE FOR LOCATING	9
DASHBOARD		EXHAUST MANIFOLDS-PAINT FOR	3
-TEXTURING METAL PARTS	2,13,17,20	FIRE FROM BAD WIRING	9
-REMOVAL.....	17	FRAME SPECIFICATIONS, 57	10
DASH PAD-DYING '57	7	FREE CLASSIFIEDS ON-LINE.....	12
DATA PLATE, EARLY/LATE '57.....	21	FRONT SUSPENSION-COIL SPRING REMOVAL.....	17
DATA PLATE RIVET TOOL	11	FRONT WHEELS-CHECKING FOR GREASE LEAKAGE	10
DECAL POSITIONS.....	4,5	FUEL GAUGE, TESTING	21
DOOR HANDLES-REMOVING.....	11	FUEL LINE, FLEXIBLE-PROBLEM.....	9
DOOR GLASS INSTALLATION TIPS.....	15	FUEL STABILIZER-REASONS FOR.....	13
DOOR LATCH, MODIFYING FOR KEYLESS LOCKING.....	8	FUSE-SPECS.....	1
DOOR LOCK BUTTONS-TOO TIGHT	6,20	GAS CAPS-VENTING TIPS.....	3
DRIVE SHAFT NUMBERING.....	12	GAS TANK-PREVENTING RUST INSIDE	13
EARLY/LATE '57, IDENTIFYING.....	21	GAUGES, TESTING FUEL & TEMP	21
ELECTRICAL		GENUINE FORD RESTORER SIGN	12
-6 VOLT TO 12 VOLT CONVERSION	20	GLASS-REMOVING WINDSHIELD GLASS	13
-6 VOLT ALTERNATOR.....	13	GLOVE BOX-OPENING WHEN STUCK.....	2
-BATTERY CABLE ROUTING & RETAINERS.....	13	HANDLING PROBLEMS.....	15
-LEAKS, LOCATING	10	HARDTOP	
-TROUBLE SHOOTING CHART.....	11	-INSTALLING LATE TRIM ON AN EARLY TOP	20
EMERGENCY BRAKE CABLE REPLACEMENT	13	-POSITION OF CREST EMBLEM.....	6
ENGINE		-REAR GLASS INSTALLATION	16
-ASSEMBLY ERRORS.....	15	-STORAGE TIP	13
-BLOCK CLEANING.....	7	HEATER CONTROL-MANUAL.....	1
-CARBURETOR, FINDING LIST NUMBERS.....	8	-MANUAL CONTROL INSTALLATION TIP	14
		HEADLAMPS-REPLACING	14

SUBJECT OF ARTICLE ISSUE(S)

HEADLIGHT SWITCH CONTROL SHAFT-REMOVAL17
HEIGHTS-PROPER-FRONT & REAR1,10
HOOD
-ADJUSTMENT17
-BLACK MARK ON UNDERSIDE20
-BUMPER-CORRECT POSITION1
HOOD RELEASE
-CABLE7
-SAFETY PULL12
-TOOL12
HORN RELAYS-MADE WRONG2
HORN RING REMOVAL12
HUBCAP-WIRE WHEEL CLIP TIP14
INVOICES-AVAILABLE1
INVOICES-DECODING ABBREVIATIONS11
JUNCTION BLOCK WIRING9
LOCK TUMBLER ASSEMBLIES-REMOVAL17
LICENSE PLATE PAINTING/RECONDITIONING13,22
LINES, CHECK BEFORE INSTALLING16
LIST NUMBERS-LOCATING8
LOCK BUTTONS-TOO TIGHT6,20
LOOSE WHEEL COVERS-PREVENTING18
LUBRICATION POINTS OFTEN MISSED11
MAILBOX-BUILDING YOUR OWN9
MAINTAINANCE SCHEDULE16
MIRROR-OUTSIDE-POSITION & FACTS3
NEUTRAL SAFETY SWITCH, ADJUSTING19
NEW ITEMS
-56 FUEL & TEMP GAGES16
-HEADLAMP DOOR RETAINER CLIP19
-MUFFLER HEAT SHIELD16
-PARK LAMP ON CONVERSION16
-TAIL LAMPS-LED18
-THIRD BRAKE LIGHT22
-WIPERS-BLADES & ARMS-LIKE ORIGINAL5
-WINDSHIELDS16
-VISOR ARMS16
-ZDDP+20
ON-LINE-FREE CLASSIFIEDS12
ONLINE-MAIL LIST11,15
OVERHEATING TIP17
PAINT
-58 COLORS ON '57'S10
-COLOR COMBINATIONS AVAILABLE8
-DASHBOARD TEXTURING2,13,17
-DASHBOARD UNDERSIDE13
-LICENSE PLATES13
-PERFECT PAINT JOB18
-PROTECTING MACHINED SURFACES WHEN PAINTING10
-PROTECTING WHEN INSTALLING HARDTOP12
-STAINS FROM WEATHERSTRIP7
PART PROBLEM
-CANVAS CONVERTIBLE TOP COVERINGS1
-DOOR WEATHERSTRIPS1
-FLEXIBLE FUEL LINE9
-GAS CAPS3
-HORN RELAY, '572
- LINES, POSSIBLE CONTAMINATION16
-MAIN WIRING HARNESS, '571
-MANUAL HEATER CONTROL14
PARTS PROBLEM
-TURN SIGNAL BULB11
-TURN SIGNAL SWITCH1
-VISOR & ARMS4,10
-WIPER BLADES-LOOSE6
-WEATHERSTRIP-STAINING PAINT7

SUBJECT OF ARTICLE ISSUE(S)

POWER STEERING HOSES, 2 TYPES21
PRICING-PARTS-TOO HIGH1
RADIATOR-KEEP CLEAN FOR MAXIMUM EFFICIENCY17
RADIATOR- TRANSMISSION COOLING21
RADIO-REMOVAL18
RADIO-TRIMMING ANTENNA7,20
REGISTRY-THUNDERBIRD18
REMOVING THE
-COIL SPRINGS17
-DASH ASSEMBLY17
-HEADLIGHT SWITCH CONTROL SHAFT17
-IGNITION & TRUNK LOCK TUMBLER ASSEMBLIES17
-RADIO18
-WINDSHIELD LOWER TRIM21
RESTORATION PARTS COSTS15
RESTORATION MANUALS13
RUG-CLASSIC T-BIRD12
RUST-ON BUMPERS13
SAFETY TIPS
-FUEL FILTER GASKET22
-FUEL LINE, FLEXIBLE-PROBLEM9
SEAT-REMOVAL TIPS14
-TRACK MAINTENANCE20
SECURITY-SAFE STORAGE TIP5
SHIFTER BOOT-PROLONGING LIFE OF6,19
SKINNED KNUCKLES MAGAZINE8
SPRINGS-FRONT INSULATOR21
-REAR, REPLACING12
STARTING PROBLEMS, ADJUST NEUTRAL SAFETY SWITCH19
STEERING COLUMN
-LOOSENING FOR ADJUSTMENT17
-SEAL-BURNING FROM EXHAUST MANIFOLD10
STEERING-WORM GEAR-INSTALLING3
STEERING WHEEL-PAINTING2
STEERING WHEEL PULLER-DIMENSIONS TO MAKE10
STORAGE TIPS14
SURVEY QUESTIONNAIRE4
TACH CABLES-CORRECT LENGTH5
TACH-REMOVING & INSTALLING NEEDLE8
TAIL LAMPS
-BRIGHTENING15
-LED'S18,22
-MEETING DOT STANDARDS18
-THIRD BRAKE LIGHT22
TEMPERATURE GAUGE, TESTING21
TIRE VALVES-SCHRADER10
TIRES-RADIALS5
TIRES-SPARE-SPACE SAVER5
TOOL
-DATA PLATE RIVET11
-HOOD RELEASE12
-STEERING WHEEL PULLER10
TOPS-SEE CONVERTIBLE TOPS & HARDTOPS
TOP SIDE CLAMP ADJUSTING14
TOUR, 48 IN 0821
TRANSMISSION
-AIR COOLED, CLOSING OFF TRANSMISSION COOLER21
-STARTING IN SECOND14
-ADJUSTING PASSING GEAR LINKAGE14
TRIVIA6
TRUNK
-55 TRUNK LIGHT20
-'57 OVERSLAM BUMPERS, INSTALLING14
-OPENING WITHOUT A KEY13
TURN SIGNAL JEWEL LOOKS CRACKED11
TURN SIGNAL SWITCH
-PROBLEM1
-REPLACEMENT PROCEDURE22

UPHOLSTERY	
-COLORS	7
-DIFFERENCES-MISC FACTS	7
-OPTIONS AVAILABLE FOR EACH PAINT CODE	8
VACUUM ADVANCE-BINDING	5
VALUE OF T-BIRDS	2
VALUE OF T-BIRDS - UPDATE	7,13,16
VIDEO ON T-BIRDS	11
VISORS-LOOSE ON SHAFT-FIX	4,10
WATER PUMP BAFFLE	7
WEATHERSTRIPS	
-DOOR-PROBLEMS	1
-INSTALLING	2
-PROTECTING FROM HOIST STRAPS	10
-STAINING PAINT	7
WHEEL BEARINGS-INSTALLATION TIPS	14
WHEEL COVERS-LOOSE-PREVENTING	18
WIRING-INSTALLING ENGINE COMPARTMENT HARNESS	16
WINDSHIELD LOWER TRIM, REMOVAL	21
WINDSHIELD-REPLACING	14
WINDSHIELD WIPER MOTOR, RECONDITIONING	19
WINDWING GLASS REMOVAL	13
WINDWING TENSIONING SLEEVE REMOVAL	12
WIPERS-BLADES & ARMS-LIKE ORIGINAL	5
WIPER BLADES - LOOSE - HOW TO FIX	6
WIPER MOTOR, RECONDITIONING	19
WIRING	
-6 VOLT TO 12 VOLT CONVERSION	20
-FIRE RESULTING FROM	9
-JUNCTION BLOCKS	9
WIRING-MAIN HARNESS PROBLEMS	1
Y BLOCK MAGAZINE	8
Y-BLOCK ASSEMBLY ERRORS	15
ZDDP+ OIL ADDITIVE	20